

EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|-------|---|---|------------------|---------|---------------------|
| L1 | 758 | (bond or bonding or solder or soldering or braze or brazeing or join or joining) near (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:17 |
| L3 | 55 | 1 and (groove or grooves or grooved or channel or channels or passage or passages or passageway or passageways) with (bond or bonding or solder or soldering or braze or brazeing or join or joining) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:18 |
| L4 | 90843 | (rotary or rotation \$5) near (disc or discs or disk or disks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:20 |
| L5 | 4 | 4 and (bond or bonding or solder or soldering or braze or brazeing or join or joining) near (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:20 |
| L6 | 1267 | 4 and (annular\$5) near2 (recess or recess or depression or depressions) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:21 |

| | | | | | | |
|-----|--------|--|---|----|-----|---------------------|
| L7 | 28 | 4 and (annular\$5) near2 (recess or recess or depression or depressions or groove or grooves or channel or channels or passage or passages or passageway or passageways) with (bond or bonding or solder or soldering or braze or brazeing or join or joining) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:26 |
| L8 | 382881 | (rotary or rotation \$5) near (shaft ot shafts) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:27 |
| L9 | 5 | 8 and (bond or bonding or solder or soldering or braze or brazeing or join or joining) near (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:28 |
| L11 | 383 | (bond or bonding or solder or soldering or braze or brazing or join or joining) near (hole or holes or via or vias or aperture or apertures) with (shaft ot shafts) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:30 |
| L12 | 2 | 11 and (bond or bonding or solder or soldering or braze or brazeing or join or joining) near2 (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:30 |
| L14 | 7 | (first) adj (bond or bonding or solder or soldering or braze or brazing or join or joining) adj (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:34 |

| | | | | | | |
|-----|----|--|---|----|-----|---------------------|
| L15 | 3 | 14 and (second or secondary) adj (bond or bonding or solder or soldering or braze or brazing or join or joining) adj (mark or marks) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:34 |
| L16 | 87 | 3 or 5 or 7 or 9 or 12 or 15 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/09/24 12:35 |

9/ 24/ 2008 12:42:29 PM

C:\ Documents and Settings\kstoner\ My Documents\ EAST\ Workspaces\ i'mback.wsp